

ROPS Good FOPS Good

Track Type Excavators Inspection Report

APPRAISAL FAMILY: TRAC	К ТҮР	E EXCAVA	TORS			
	Accour	nt Manager:K	Levin Shanlo	ev	Inspection Date	:7/6/2022
Inspector:C						
Location:S					Approved Date	:7/7/2022
					Expiration Date	:9/5/2022
MACHINE DETAILS						
		Manufactur	er:AA	Model:349E	S/	N:0TFG00787
		Ye	ar:2013	Eng S/N:TXM03955	Eng S/N:TXM03955 Trans S/N:HYSTAT	
		SMU/H	rs:10776	Hours Date:7/6/2022		
		Last Schedu		Last CTS:	Last Pl	M:
Date C		ole Sent to La		2 Oil Sample: ENGINE HYDRA	ULIC	
		commendation				
TRACK TYPE EXCAVATOR	S CON	FIGURATI	ON			
ECM Download: Yes			S READY:			Inquire for options on
Enclosed Cab: Yes			Open Cab:			Yes
Auxiliary Hydraulics: No			, Leveling:		Boom, One Piece:	Yes
Boom, Two Piece: No				22 FT 7 IN	Boom Check Valve:	
Stick, Long: No	INI		, Medium:		Stick, Short:	
Stick Length: 12 FT 6 Bucket Size: 28 IN	IIN		eck Valve: Hydraulic:		Coupler, Quick: Thumb, Mechanical:	Yes No
Track Shoe Width/Type: 747 MM	I TG	High Ambie			Guarding:	No No
Engine Tier Rating: TIER 41			1 Changer:		Cab Riser:	
Auto-Lube: No	-	Straight Tr			Product Link:	
Anti-Theft System: No				COMPLETE WITH REPAIRS NEEDED		
GENERAL APPEARANCE		•			•	
	CODE		REMARI	ZQ		
	Good		KEMIAKI	A.S		
	Good					
	Good					
	Good					
Catwalk	Not Ap	plicable				
	Good					
	Good					
-	Good					
	Good					
	Good					
Car Body Good						
	Bumper Good Counterweight Good					
	Good					
	Good					
	Good					
Grab Irons	Good					
	Good					
	Good					
Ę.	Good		ENIODIE	HIVIDD AT LIC		
	Yes No		ENGINE I	HYDRAU;IC		
	Yes		HEAVVS	OIL AND OIL FROM THE LEAKING CYLINDE	PS	
<u> </u>		LETE AND		ONAL WITH NORMAL WEAR FOR THE AGE		
Tietes	COIVII	BETETHIE	OT LIGHT		TE OF THE CITE	
SAFETY ITEMS				·		
CODE			REMARI	KS		
Safety Decals In Place	Yes					
Safety Decals Legible						
ROPS Good		I				



Track Type Excavators Inspection Report

Horn	Good		
Travel Alarm	Good	TRAVEL ALARM IS INOP	
Swing Brake	Good		
Brake Hold	Good		
Notes	COMPLETE WITH REPAIRS NEEDED		



GAUGES, OPERATOR STAT	ΓΙΟΝ, CONSOL	E
	CODE	REMARKS
Dash Console	Good	
Meter	Good	
Gauges	Good	
Switches	Good	
Wipers	Good	
Air Conditioner	Good	
Heater	Good	
Interior Lights	Good	
Seat Cushions / Arm Rests	Good	SEAT CUSHIONS WORN WITH HOLES, ARM RESTS WORN AND TAPED, SEAT SUSPENSION LEAKING AND WILL NOT HOLD ADJUSTMENT
Floor Boards	Good	
EMS Panel / Warnings	Good	
Doors	Good	
Door Latches	Good	
Glass / Mirrors	Good	UPPER FRONT CAB GLASS CRACKED
Seat Belt	Good	
Hyd Controls		
Parts Book	No	
Safety Manual	No	
O&MM	No	
ROPS Cert Plate	Yes	
Notes	COMPLETE WI	TH REPAIRS NEEDED



















ENGINE	7
ENGIN	<i>y</i>

	CODE	REMARKS
Oil Leaks	No	
Blow By	No	
Knocking	No	
Compression In Radiator	No	
Water In Oil	No	
Fluid Levels OK?	Yes	
EPA Decal	Yes	
Anti-freeze Color	RED	
Oil Pressure (H/L/W)	51/39	
Smoke (B/D/L/W)	NORMAL	
Operating Condition	Good	
Turbocharger / Blower	Good	
Fuel Injection System	Good	
Governor	Good	
Engine Supports	Good	
Air Cleaners	Good	
Exhaust / Muffler	Good	
Belts / Pullys	Good	
Oil Filter Condition	Good	
(Cut)	No	
Notes	COMPLETE AND	OPERATIONAL WITH NORMAL WEAR FOR THE AGE AND HOURS









COOLING SYSTEM











Track Type Excavators Inspection Report

Coolers	Good	
Hoses	Good	
Water Pump	Good	
Fan	Good	
Fan Drive	Good	
Notes	COMPLETE AND	OPERATIONAL WITH NORMAL WEAR FOR THE AGE AND HOURS





ELECTRICAL, STARTING AND CHARGING SYSTEM

	CODE	REMARKS
Batteries / Cables	Good	BATTERIES HAVE RECIENTLY BEEN REPLACED WITH NEW
Starter	Good	
Alternator	Good	
Wiring	Good	
Pre-Heater	Good	
Lighting	Good	UPPER RIGHT CAB MOUNTED WORK LIGHT MISSING
Ether Aid	Yes	
Block Heater	No	
Notes	ODED ATIONAL W	/ITH DEDAIDS NEEDED

Notes OPERATIONAL WITH REPAIRS NEEDEL





FINAL DRIVES

	CODE	REMARKS
Plantaries / Differential	Good	
Housings	Good	
Drive Motors	Good	
Guards	Good	
Notes	COMPLETE AND	OPERATIONAL WITH NORMAL WEAR FOR THE AGE AND HOURS









воом

	CODE	REMARKS
Pins / Bushings	Good	
Boom Condition	Good	
Boom Pins	Good	
Boom Length	20 FT 7 IN	







STICK

	CODE	REMARKS
Pins / Bushings	Good	
Stick Condition	Good	
Stick Pins	Good	STICK PIN FLAG RETAINER BOLT AND SPACER MISSING
Stick Length	12 FT 8 IN	
Notes	COMPLETE AND	ODED ATION AT WITH MODIMAL WEAD FOR THE AGE AND HOURS







HYDRAULICS

	CODE	REMARKS
Operating Condition	Good	
Boom Cylinder	Good	BOTH BOOM CYLINDERS LEAKING AT ROD SEALS
Stick Cylinder	Good	
Bucket Cylinder	Good	BUCKET CULINDER LEAKING AT ROD SEALS
Thumb Cylinder	Not Applicable	



Carrier Rollers Good
Idlers Good
Track Rollers Good

Track Type Excavators Inspection Report

Hose Lines	Good	
Pumps & Valves		
Tank	Good	
Pump Drive		
	Good	
Swing Gear		
		OIL LEAKS IN THE AREA OF THE RIGHT SWING DRIVE MOTOR
	Good	
Hydraulic Swivel Filter Condition	Good	
(Cut)		
	GOOD	
		H REPAIRS NEEDED
ATTACHMENTS / WORK TO	OOLS	
	CODE	REMARKS
Hammer		
Thumb	No	
Vibratory Plate		
Auger		
Claw		
Crusher		
Grapple Pulverizer		
Tilting Ditch Bkt		
Rake		
Shear		
Ripper		
Other		
Other	No	
Notes		
BUCKET		
	CODE	DEM A DIZO
Cutting Edge		REMARKS
Teeth / Adapters		
Bucket Bottom		
Bucket Sides		
Bucket Linkage		
Bucket Mounts	Good	
	СР	
Width		
Serial Number		
Quick Coupler		
Brand Notes		OPERATIONAL WITH NORMAL WEAR FOR THE AGE AND HOURS
Notes	COMPLETE AND	OF ERATIONAL WITH NORMAL WEAR FOR THE AGE AND HOURS
UNDERCARRIAGE		
		REMARKS
Track Frame Left		
Track Frame Right		
Track Pitch		
Pins & Bushings Turned?		
Track Shoes Regrousered? Link Part No.		
Link Assemblies		
Track Shoes		
- 11000		



Track Type Excavators Inspection Report

	LEFT TRACK	RIGHT TRACK	LEFT % WORN	RIGHT % WORN
Link	128.00	127.00	10.00	15.00
Bushing	70.00	71.00	45.00	27.00
Shoe	30.00	29.00	18.00	24.00
C/Roller	179.50	179.00	8.00	8.00
Idlers	21.00	21.00	10.00	10.00
Rollers	195.00	192.00	25.00	40.00
Sprockets	Good			

Notes COMPLETE AND OPERATIONAL WITH NORMAL WEAR FOR THE AGE AND HOURS



SERVICE

	CODE	REMARKS
Service Needed		

GENERAL REPAIRS AND REMARKS

Repairs Needed: RIGHT UPPER CAB MOUNTED WORK LIGHT MISSING SEAT CUSHION COVERS WORN WITH HOLES BUCKET CYLINDER
LEAKING AT ROD SEALS BOTH LEFT AND RIGHT BOOM CYLINDERS LEAKING AT ROD SEALS FRONT UPPER CAB GLASS
CRACKED ARM RESTS WORN RETAINER BOLT AT STICK PIN FLAG AT COUPLER MISSING

General comments: OPERATIONAL WITH REPAIRS NEEDED.

