

APPRAISAL FAMILY	: ASPHALT PAVI	ERS							
		ager:Billy Pikula				Insne	ctio	n Date:1/31/2020	
Inspector:Jim Lockhart					Report Date:2/6/2020				
	Loca	tion:Eloy, AZ.						d Date:3/5/2020	
						Expira	atio	n Date:5/4/2020	
MACHINE DETAILS									
	Ma	anufacturer:AA			Model:PM			S/N:0PNM00280	
		Year:2017 SMU/Hrs:6614			g S/N:RF	1X10372 /15/2020		Γrans S/N:	
	Las	t Schedule:	T		CTS:	713/2020		Last PM:11/19/2019	
	Date Oil Sample S			Oil Sa					
	Recomn	nendations:No r	eportab	le issues - res	sults are	attached			
ASPHALT PAVER C	ONFIGURATION								
ECM Download:						Product Link:		Anti-Theft:	
Auto Grade Control:	Yes Inspection form is f	or acabalt payo	re plac	neo lico como		Auto Slope Control:			
Comments:	flexibility when revi	or aspriait pave ewing certain se	ections o	of report	7	Engine Tier Rating:		Extend-A-Mat-Screed:	No
Min:	6.9ft Cutter drum			•		Max:		Feeder Control:	
Grade Sensors:						High Ambient Cooling:		Hyd Truck Hitch: Paddle:	
Lights: Power Crown Control:						Night Paving Gen Sys:		Paddle: Power Slope Control:	
Product Link:						Push Rollers:		Rubber Track Width:	. 10
Screed:						Sonic:	Nο	Steel Trk Shoe Width:	14in
Tire Size:	-					Wand:		- I I I I I I I I I I I I I I I I I I I	TRACKS
						vvanu.	INO		
GENERAL APPEAR									
		CODE	REMA	RKS					
	tor Grill & Shroud Engine Enclosure								
	Hood / Stack								
	Fuel Tank								
	Battery Box								
	lain Frame Welds Pre-Cleaner Bowl								
<u> </u>	Steps / Ladder								
	Grab Irons								
	Paint	Good Not Applicable							
	Screed Frame								
	Sheet Metal		Side do	oor on right si	ide need	s to be shimmed - door	r hai	ngs up	
	Notes		1_						
	SOS Taken Cleaning Required					ached to report			
	neaning Required	res	Clean	for transport a	and delive	ery			
								THE PARTY NAMED IN	1
370	6	STATE OF THE PARTY	156			20/12 - 816			
<u>p</u>	هِ هِ	ø		ø	ø	م م		g g	
	or I								
p p									
SAFETY ITEMS									
OAI ETT TIEMO		CODE	DEMA	DIC					
CODE Safety Decals In Place Yes		REMA	n no						
Safety Decals Legible Yes									
	Seat Belt	Not Applicable							
Back-Up Alarm Good Horn Good									
Parking Brake Good									
		Good							
	Notes								
GAUGES, OPERATO									



Asphalt Pavers Inspection Report

	CODE	REMARKS
Dash Console	Good	
Meter	Good	Unable to scroll to hour meter - last recorded hours were 6614hrs on 11/19
Gauges	Good	
Switches	Fair	Discharge belt joy stick on right side console does not swing belt to the left
Seat Cushions / Arm Rests	Not Applicable	
Floor Boards	Good	
EMS Panel / Warnings	Good	
Platform	Good	
Parts Book	No	
Safety Manual	Yes	
O&MM	Yes	
Notes		















	\sim	IN	_

LINGINE		
	CODE	REMARKS
Oil Leaks	No	No observable leaks
Blow By	Yes	Light wisps of blow by visible at idle - assess
Knocking	No	
Compression In Radiator	No	
Water In Oil	No	
Fluid Levels OK?	No	
EPA Decal	Yes	
Anti-freeze Color	RED	
Oil Pressure (H/L/W)	NORMAL	
Smoke (B/D/L/W)	NORMAL	
Operating Condition	Good	
Turbocharger / Blower		
Fuel Injection System	Good	
Governor	Good	
Engine Supports	Good	
Air Cleaners		
Exhaust / Muffler	Good	
Belts / Pullys	Good	
Oil Filter Condition (Cut)	NI	
Notos	Sama lagged of	adde for angine over speed and high exhaust tomps

Notes Some logged codes for engine over speed and high exhaust temps















COOLING SYSTEM

	CODE	REMARKS
Radiator	Good	
Coolers	Good	
Hoses	Good	
Water Pump	Good	
Fan	Good	
Fan Drive	Good	
Leaks	Good	No observable leaks
Notes		





ELECTRICAL, STARTING AND CHARGING SYSTEM

	CODE	REMARKS
Batteries / Cables	Good	
Starter	Good	
Alternator	Good	
Wiring	Good	
Pre-Heater	N	
Lighting	Good	
Notes	All ground contr	ol functions performed satisfactory - grade controls were not inspected
Ether Aid	No	
Block Heater	No	



Asphalt Pavers Inspection Report



















FINAL	DRIVES
-------	--------

	CODE	REMARKS
Planetaries / Diff	Poor	Right side final drives appeared to be locking up - assess and repair
Housings	Good	
Notes	Tracks on right side would intermittently bind up - tracks would try and crawl up sprockets - could not get them to duplicate issue at will - grinding noise coming from track groups when it occurs - could also possibly be within drive motors	


No observable leaks Leaks











	CODE	REMARKS
Hydraulic Tank	Good	
Pumps / Valves	Good	
Hoses / Fittings	Good	
Auger Hoist Cyl	Good	
Hopper Cyls	Poor	Cutter side door cylinders bleed off
Grade Control Cyls	Good	
Screed Hoist Cyls	Good	_

Truck Hitch Cyl Not Applicable Hyd Filter N Left door cylinder is leaking Leaks Yes






















PAVER / SCREED / CONVEYOR

	CODE	REMARKS
Operating Condition	Good	
Conveyor	Good	
Conveyor Chains, Rollers & Sprockets	Not Applicable	
	Good	
Hopper	Good	Flashing is in good condition
Hopper Hinge Pins & Tubes	Not Applicable	
Truck Hitch	Not Applicable	
Push Rollers	Not Applicable	
Steering Linkage	Good	
Screed Plates	Not Applicable	
Screed Frames	Not Applicable	
Thickness Screws	Not Applicable	
Crown Adjustment	Not Applicable	
Ext. Screed Height Adjustment	Not Applicable	
Ext. Screed Slope Control Adj.	Not Applicable	
Chrome Guide Tubes	Good	
Screed Burners	Not Applicable	
Auto Grade / Slope Control	NI	
Ski Leveling	Not Applicable	
Auger	Good	
Auger Motors	Good	
Ignitors	Not Applicable	
Vibrators	Not Applicable	
Metering Gates	Good	Cutting edge on cutter door has moderate wear - no repairs at this time
Vent System	Good	
Leaks		No observable leaks
Notes	Did not see any	repairs to top of cutter - cutter wheel performed fine







UNDERCARRIAGE		
	CODE	REMARKS
Track Frame Lef	Good	
Track Frame Righ	t Good	
Rubber Track / Belt Lef		
Rubber Track / Belt Righ	t Good	
Cleats / Grousers	Good	
Idlers	Good	
	Good	
Front Bogies		
Drive Tires Size		
Steering Tires Size		
Wheels	Good	
Track Tension Sys	Good	
Notes Undercarriage		is in overall good condition and can be run out
Tires/UC Needed	1	

SERVICE

CODE F	REMARKS
Service Needed	No service due

GENERAL REPAIRS AND REMARKS

Repairs Needed: Final drives - cutter side door - hydraulic leaks - belt joy stick - engine blow-by - hard starting

General comments: Machine runs - cutter operates fine - system controls work fine with the exception of the discharge belt joy stick - overall condition is fair to good

