



EXCAVATOR BUCKET INSPECTION

Inspection Information

| | |
|----------------------|---------------|
| Inspector ID: | 2654 |
| Inspection Date: | 04/22/2021 |
| Inspection Location: | Eloy, Arizona |

General Information

| | |
|-------------------------|--|
| Manufacturer: | Werk-Brau |
| Inventory ID: | E168203 |
| Serial Number: | BU.E168203 |
| Part Number: | N/A |
| Type/Duty/Application: | Standard Duty |
| Width (Inches): | 25" |
| Capacity (Cubic Yards): | 0.16 |
| Linkage: | 304 Linkage |
| Interface: | Pin On |
| Compatibility: | 303C CR, 303.5, 303.5C/D/E CR, 304D/E CR |
| Overall Condition: | Good - Moderate Wear (No Major Damage) |
| General: | BUCKET IS IN GOOD SHAPE. ONE EAR IS SLIGHTLY BENT OUTWARDS |

Pin Specifications

| | |
|-----------------------------------|--|
| Bucket Pins Included: | Included |
| Stick Pin Diameter (Millimeters): | 40mm |
| Link Pin Diameter (Millimeters): | 40mm |
| Face Spread (Millimeters): | 136mm |
| Pin Spread (Millimeters): | 200mm |
| Pins Condition: | Good - Moderate Wear (No Major Damage) |
| Pins Notes: | |

Additional Information

| | |
|------------------------------|--|
| Cutting Edge: | Not Included |
| Teeth / Tips: | Included |
| Side Cutters: | Not Included |
| Side Protectors: | Not Included |
| Lifting Eye: | Not Included |
| Drain Holes: | Not Included |
| Grapple: | Not Included |
| Cylinders / Lines: | Not Included |
| Cylinders / Lines Condition: | No Cylinders or Lines Required |
| G.E.T. Overall Condition: | Good - Moderate Wear (No Major Damage) |
| Wear Item Notes: | OUTSIDE TEETH ARE WEARING FASTER THAN CENTER |

Disclosure: Inspection, configuration, compatibility and condition should be confirmed before purchasing. All information is subject to change due to the inherent risk of inaccurate information. Call 480-633-4150 for additional details.

