

APPRAISAL FAMILY: COMPACTORS - ASPHALT (CB)

| | |
|----------------------------|---------------------------|
| Account Manager:Mike Riffe | Inspection Date:5/18/2021 |
| Inspector:Jim Gabriel | Report Date:5/19/2021 |
| Location:Eastmark | Approved Date:5/25/2021 |
| | Expiration Date:7/24/2021 |

MACHINE DETAILS

| | | |
|---------------------------------------|----------------------|-------------------|
| Manufacturer:VO | Model:DD120B | S/N:287072 |
| Year:2015 | Eng S/N:11611329 | Trans S/N:n/a |
| SMU/Hrs:2318 | Hours Date:5/18/2021 | |
| Last Schedule: | Last CTS: | Last PM:7/22/2020 |
| Date Oil Sample Sent to Lab:5/19/2021 | Oil Sample:Engine | |
| Recommendations: | | |

COMPACTOR CONFIGURATION

| | | | | | |
|------------------|------|--------------------|-----|---------------------|-------------------|
| ROPS: | | Product Link: | | EROPS: | No |
| OROPS: | Yes | Air Conditioning: | No | Heater: | No |
| Drum Width: | 79IN | Vibratory System: | Yes | Water Spray System: | Yes |
| Lighting System: | Yes | Anti-Theft System: | No | Engine Tier Rating: | Tier four Interim |
| Comment: | | Product Link: | No | | |

GENERAL APPEARANCE

| | CODE | REMARKS |
|-------------------|----------------|---|
| Radiator Grill | Good | |
| Shroud | Good | |
| Engine Enclosure | Good | |
| Hood / Stack | Good | |
| Fuel Tank | Good | |
| Crankcase Guard | Good | |
| Battery Box | Good | |
| Front Frame | Good | |
| Rear Frame | Good | |
| Pre-Cleaner Bowl | Good | |
| Cab | Not Applicable | |
| Canopy | Good | |
| Steps / Ladders | Good | |
| Grab Irons | Good | |
| Paint | Good | |
| Sheet Metal | Fair | Access panel at right rear and rear center of machine have a couple of broken mounting bolts. |
| Guards / Screens | Good | |
| SOS Taken | Yes | Engine SOS obtained. |
| Cleaning Required | Yes | |


SAFETY ITEMS

| | CODE | REMARKS |
|-------------------------------|------|---------|
| Safety Decals In Place | Yes | |
| Safety Decals Legible | Yes | |
| ROPS | Yes | |
| Articulation Safety Bar / Pin | Yes | |
| Parking Brake | Good | |
| Horn | Yes | |
| Back-Up Alarm | Yes | |


GAUGES, OPERATORS STATION, CONSOLE



| | CODE | REMARKS |
|--------------|------|------------|
| Dash Console | Good | |
| Meter | Good | 2318 Hours |
| Gauges | Good | |
| Switches | Good | |

| | | |
|--------------------------|----------------|-------------------------------------|
| Wipers | Not Applicable | |
| Air Conditioner | Not Applicable | |
| Heater | Not Applicable | |
| Interior Light | Not Applicable | |
| Seat Cushions | Fair | Seat cushion is weathered and torn. |
| Arm Rests | Good | |
| Floor Boards | Good | |
| EMS Panel / Warnings | Good | |
| Doors | Not Applicable | |
| Door Latches | Not Applicable | |
| Glass / Mirrors | Not Applicable | |
| Seat Belt | Fair | Seat belt has no date tags. |
| Hydraulic Controls | Good | |
| Parts Book | No | |
| Safety Manual | No | |
| O&MM | No | No manuals. |
| ROPS Certification Plate | Yes | |




ENGINE

| | CODE | REMARKS |
|-------------------------|--------|---------|
| Oil Leaks | No | |
| Blow-By | No | |
| Knocking | No | |
| Compression In Radiator | No | |
| Water In Oil | No | |
| Fluid Levels OK | Yes | |
| EPA Decal | Yes | |
| Antifreeze Color | Red | |
| Oil Pressure (H/L/N) | Normal | |
| Smoke (B/D/L/W) | Normal | |
| Operating Condition | Good | |
| Turbocharger / Blower | Good | |
| Fuel Injection System | Good | |
| Governor | Good | |
| Engine Supports | Good | |
| Air Cleaners | Good | |
| Exhaust / Muffler | Good | |
| Oil Filter Condition | NI | |
| Cut | No | |



COOLING SYSTEM

| | CODE | REMARKS |
|----------------|------|---------|
| Radiator | Good | |
| Coolers | Good | |
| Hoses | Good | |
| Water Pump | Good | |
| Belts / Pullys | Good | |
| Fan | Good | |
| Fan Drive | Good | |
| Leaks | No | |



ELECTRICAL SYSTEM

| | CODE | REMARKS |
|--------------------|------|-----------------------|
| Batteries / Cables | Good | |
| Starter | Good | |
| Alternator | Good | |
| Wiring | Good | |
| Pre-Heater | Good | |
| Lighting System | Good | All lights functional |
| Ether Aid | No | |

| | | |
|--|-------------|-----------------------|
| Block Heater | | No |
|       | | |
| STEERING SYSTEM | | |
| | CODE | REMARKS |
| Steering Linkage | Good | |
| Articulation Pins & Bushings | Good | |
| Steering Cylinders | Good | |
| Steering Pumps / Valves | Good | |
| Hand Metering Unit | Good | |
| Hoses / Fittings | Good | |
|      | | |
| HYDRAULIC SYSTEM | | |
| | CODE | REMARKS |
| Tank | Good | |
| Pumps / Valves | Good | |
| Hoses / Fittings | Good | |
| Propel Pump | Good | |
| Propel Motor | Good | |
| Vibratory Pump | Good | |
| Vibratory Motor | Good | |
| Filter Condition (Cut) | NI | |
| Leaks | No | No leaks. |
|        | | |
| DRUMS | | |
| | CODE | REMARKS |
| Drum Width | 79IN | |
| Drum Surface | Good | |
| Drum Scrapers | Good | |
| Drum Hubs | Good | |
| Drum Drive Planetaries | Good | |
| Cleaner Bars | New | |
| Vibratory System | Good | |
| Isolators | Good | |
| Water Spray Bars / Nozzles | Good | |
|             | | |
| SERVICE | | |
| | CODE | REMARKS |
| Service Needed | No | Current on PM service |
|  | | |
| GENERAL REPAIRS AND REMARKS | | |
| Repairs Needed: Seat cushion torn, Seat belt has no date tag, Broken bolts for access covers. | | |
| General comments: Machine is complete and operational. | | |
|            | | |

