

APPRAISAL FAMILY: TRAILER

Account Manager: Mark Snow

Inspection Date: 6/30/2021

Inspector: Ryan Earl

Report Date: 7/1/2021

Location: Mesa

Approved Date: 7/2/2021

Expiration Date: 8/31/2021

MACHINE DETAILS

Manufacturer: C7

Model: M-39P

S/N: 4X4TCKR20DX114835

Year: 2012

Eng S/N:

Trans S/N:

SMU/Hrs: 9999

Hours Date: 6/30/2021

Last Schedule:

Last CTS:

Last PM:

Date Oil Sample Sent to Lab:

Oil Sample:

Recommendations:

TRAILER CONFIGURATION

Pintal Hitch:	No	Ball Hitch:	Yes	5th Wheel Hitch:	No
Gooseneck:	No	No. Of Axles:	2	Ramps:	No
Tire Size:	235/80R16	Comment:		Comment:	

GENERAL APPEARANCE

	CODE	REMARKS
Hitch	Good	
Tongue	Good	2100LB Tounge WT
Safety Chains	Good	
Trailer Jack Stand	Good	
Fenders	Good	
Main Frame Welds	Good	
Floor	Good	
Ramps	Not Applicable	
Paint	Fair	
Steps	Good	
Sheet Metal	Not Applicable	
Wheels	Good	
Axles	Good	
Suspension	Good	
Brakes	NI	
Lights	NI	
Wiring	Good	
Reflectors	Fair	
Notes		



SAFETY ITEMS

	CODE	REMARKS
Safety Decals	Yes	
Cleaning Required	Yes	Interior and exterior general wash for transport and delivery, refrigerator had rotten food in it, pungent sewer smell inside trailer.

TIRES

MAKE S/N	TREAD DEPTH 1/32"	% LIFE LEFT	RECAPPED	TREAD CUT/CHUNKS	SIDE CUTS SECTIONS
Right Front Outer		0.00	0.00	NA	NA
Right Front Inner	Freestar Radial S/T	9.00	90.00	No	No
R Center Outer		0.00	0.00	NA	NA
R Center Inner		0.00	0.00	NA	NA
Right Rear Outer		0.00	0.00	NA	NA
Right Rear Inner	Freestar Radial S/T	9.00	90.00	No	No
Left Rear Outer		0.00	0.00	NA	NA
Left Rear Inner	Freestar Radial S/T	9.00	90.00	No	No
L Center Outer		0.00	0.00	NA	NA
L Center Inner		0.00	0.00	NA	NA
Left Front Outer		0.00	0.00	NA	NA
Left Front Inner	Freestar Radial S/T	9.00	90.00	No	No
Tire Size 235/80R16					
Average Life Left 90					
Lug Nuts Tight No					
Spare No					
Notes Tires like new.					



SERVICE

CODE	REMARKS
Service Needed	

GENERAL REPAIRS AND REMARKS

Repairs Needed: Exterior panels have contact marks, pungent smell.

General comments:

