



Off Highway Trucks Inspection Report

Inspection Date: 5/11/2022

MACHINE DETAILS			
Manufacturer: AA		Model: 793F	
Year: 2010		Eng S/N: B7B02132	
SMU/Hrs: 38155		Hours Date: 5/11/2022	
Last Schedule:		Last CTS:	
Date Oil Sample Sent to Lab:		Oil Sample: HISTORY ATTACHED	
Recommendations:			
OFF HIGHWAY TRUCK CONFIGURATION			
Air Conditioner:	Yes	Body Liner:	No
Tail Gate:	No	Side Boards:	No
Retarder:	No	Fast Fuel:	Yes
Engine Tier Rating:	TIER 2	Tire Size:	40.00R57
Anti-Theft System:	No	Comments:	
ECM Download:	Yes	Articulated Truck:	No
Product Link:	Inquire for options on		
Heated Bed:	No	Auto Traction Cont:	Yes
		Hi Speed Oil Change:	No
		Product Link:	No
		Bed Configuration:	
		Non Articulated Truck:	Yes
GENERAL APPEARANCE			
CODE	REMARKS		
Radiator Grill & Shroud	Good		
Engine Enclosure	Good		
Hood / Stack	Good		
Fenders	Good		
Fuel Tank	Good		
Crankcase Guard	Good		
Battery Box	Good		
Main Frame Welds	Good		
Diff Supports	Good		
Bumper	Good		
Counterweight	Good		
Pre-Cleaner Bowl	Good		
Cab	Good		
Steps / Ladder	Good		
Grab Irons	Good		
Paint	Good		
Engine Doors	Good		
Sheet Metal	Good		
Car Body	Good		
SOS Taken	No		
Cleaning Required	Yes	SOME GREASE IN AREAS	
Notes	COMPLETE AND OPERATIONAL WITH NORMAL WEAR FOR THE AGE AND HOURS.		
			
SAFETY ITEMS			
CODE	REMARKS		
Safety Decals In Place	Yes		
Safety Decals Legible	No		
Articulation Safety Bar & Pins	Good		
Horn	Good		
Parking Brake	Good		
ROPS	Yes		
Notes	COMPLETE WITH NORMAL WEAR FOR THE AGE AND HOURS.		

Off Highway Trucks Inspection Report

		
GAUGES, OPERATOR STATION, CONSOLE		
	CODE	REMARKS
Dash Console	Good	
Hour Meter	Good	
Gauges	Good	
Switches	Good	
Wipers	Good	
Air Conditioner	Good	
Heater	Good	
Interior Lights	Good	
Seat Cushions / Arm Rests	Good	
Floor Boards	Good	
EMS Panel / Warnings	Good	
Doors	Good	
Door Latches	Good	
Glass / Mirrors	Good	
Bed Control	Good	
Seat Belt	Good	
Parts Book	No	
Safety Manual	No	
O&MM	No	
Back-up Alarm	Yes	
ROPS Cert Plate	Yes	
Notes	COMPLETE WITH NORMAL WEAR FOR THE AGE AND HOURS.	
		
ENGINE		
	CODE	REMARKS
Oil Leaks	No	
Blow By	No	
Knocking	No	
Compression In Radiator	No	
Water In Oil	No	
Fluid Levels OK?	Yes	
EPA Decal	No	
Anti-freeze Color	RED	
Oil Pressure (H/L/W)	I110/93	
Smoke (B/D/L/W)	NORMAL	
Operating Condition	Good	
Turbocharger / Blower	Good	
Fuel Injection System	Good	
Governor	Good	
Engine Supports	Good	
Air Cleaners	Good	
Exhaust / Muffler	Good	
Belts / Pullys	Good	
Engine Brake	Good	
Oil Filter Condition (Cut)	NI	
Notes	COMPLETE WITH NORMAL WEAR FOR THE AGE AND HOURS.	

Off Highway Trucks Inspection Report

									
COOLING SYSTEM									
	CODE	REMARKS							
Radiator	Good	MESABI CORE							
Coolers	Good								
Hoses	Good								
Water Pump	Good								
Fan	Good								
Fan Drive	Good								
Leaks	No								
Notes	COMPLETE WITH NORMAL WEAR FOR THE AGE AND HOURS.								
									
ELECTRICAL, STARTING AND CHARGING SYSTEM									
	CODE	REMARKS							
Batteries / Cables	Good								
Starter	Good								
Alternator	Good								
Wiring	Good								
Pre-Heater	Good								
Lighting	Good								
Ether Aid	No								
Block Heater	No								
Notes	COMPLETE WITH NORMAL WEAR FOR THE AGE AND HOURS.								
									
TRANSMISSION									
	CODE	REMARKS							
Transmission - Type	6 SPD PS								
Case	Good								
Controls	Good								
Seals	Good								
Torque Converter	Good								
Universal Joints	Good								
Temp / Pressure Gauges	Good								
Lines / Fittings	Good								
Transmission - Forward Shifts	Good								
Transmission - Reverse Shifts	Good								
Pump	Good								
Cooler	Good								
Drive Shaft	Good								
Retarder	Good								
Oil Filter Condition	Good								
(Cut)	No								
Operating Condition	Good								
Transmission - Noisy	No								
Leaks	No								
Notes	COMPLETE WITH NORMAL WEAR FOR THE AGE AND HOURS.								
									
STEERING									
	CODE	REMARKS							
Front Axle	Good								
Steering Linkage	Good								
Steering Gear Box	Good								
Tie Rods / Rod Ends	Good								

Off Highway Trucks Inspection Report

Steering Valves / Pumps	Good	
Steering Cylinder	Good	STEERING CYLINDERS RESEALED
Steering Tank	Good	
Pivot Pins & Bushings	Good	
Articulation Pins & Bushings	Good	
Suspension Cylinders	Good	RIGHT FRONT STRUT RESEALED
Notes	COMPLETE WITH NORMAL WEAR FOR THE AGE AND HOURS.	
Torsion Rods	Good	
Trunnions	Good	
   		




BRAKES

CODE			REMARKS		
Type (Pedal / Lever)	PEDAL				
Type (Wet, Dry)	WET				
Drums / Rotors					
Control Valve	Good				
Pump	Good				
Lines	Good				
Master Cylinder	Good				
Compressor	Good				
Brake Linkage	Good				
Accumulators	Good				
Parking Brake	Good				
Brakes Holding In What Gear	1ST				
Notes	COMPLETE WITH NORMAL WEAR FOR THE AGE AND HOURS.				
					

FINAL DRIVES

CODE		REMARKS
Wheel Lugs & Rims	Good	
Rear Final Drives	Good	
Rear Axle	Good	
Differential	Good	
Torsion Rods	Good	
Trunion / Wishbone	Good	
Leaks	No	
Notes	COMPLETE WITH NORMAL WEAR FOR THE AGE AND HOURS.	
		

HYDRAULICS

CODE		REMARKS								
Suspension Cylinders	Good									
Operating Condition	Good									
Tank	Good									
Lift Cylinders	Good									
Hose Lines	Good									
Pumps & Valves	Good									
Control Linkage	Good									
Filter Condition (Cut)	NI									
Leaks	No									
Notes	COMPLETE WITH NORMAL WEAR FOR THE AGE AND HOURS.									
										
										


Off Highway Trucks Inspection Report

TRUCK BODY		
	CODE	REMARKS
Bed Liner	Good	
Sides & Side Boards	Good	
Ribs & Stringers	Good	
Hinge Pins & Brackets	Good	
Overhang	Good	
Bottom	Good	
Pads	Good	
Safety Pins	Good	
Tailgate	Good	
Rock Knockers / Mud Flaps	Good	
Heated Body	No	
Notes	BODY NOT INCLUDED WITH THIS REPORT	

TIRES						
	MAKE S/N	TREAD DEPTH 1/32"	% LIFE LEFT	RECAPPED	TREAD CUT/CHUNKS	SIDE CUTS SECTIONS
Right Front		0.00	0.00			
Right Center		0.00	0.00			
Right Rear Outer		0.00	0.00			
Right Rear Inside		0.00	0.00			
Left Rear Outer		0.00	0.00			
Left Rear Inside		0.00	0.00			
Left Center		0.00	0.00			
Left Front		0.00	0.00			
Tire Size						
Average Life Left						
Spare	No					
Notes	TIRES NOT INCLUDED WITH THIS REPORT					
Tires Needed						

SERVICE		
	CODE	REMARKS
Service Needed		

GENERAL REPAIRS AND REMARKS	
Repairs Needed: COMPLETE AND OPERATIONAL WITH NORMAL WEAR FOR THE AGE AND HOURS. CHASSIS IS IN THE DISASSEMBLY PROCESS.	
General comments: THIS CHASSIS IS IN THE DISASSEMBLY PROCESS AND IS COMPLETE WITH NORMAL WEAR FOR THE AGE AND HOURS. TIRES AND DUMP BODY NOT INCLUDED IN THE REPORT	



Off Highway Trucks Inspection Report

