

		ΓORS				
Ac	ccount Manager:Lanc				Inspection Date: 6/2	
	Inspector:Ryan				Report Date:6/2	4/2022
	Location: EMF	PIRE ELO	Y		Approved Date: Expiration Date:	
A CHINE DETAIL C					Ехріганоп Date.	
MACHINE DETAILS	26.0			27.110070	G 2.7	054704054
	Manufacture	er: AA ar: 1990		Model:235C Eng S/N:08Z58189	S/N Trans S/N	:05AF01071
	SMU/H			Hours Date: 6/22/2022	TIALIS 5/IN	•
	Last Schedu		Last CTS: Last PM:			:
Date C	Oil Sample Sent to La	ıb:6/22/20	22	Oil Sample:ENG, HYD		
	Recommendation	ıs:				
RACK TYPE EXCAVATOR	S CONFIGURATION	ON				
ECM Download: No			GPS READY:	No	Product Link:	Inquire for options or
Enclosed Cab: Yes			Open Cab:		Air Conditioner:	
Auxiliary Hydraulics: No			Blade, Leveling:	No	Boom, One Piece:	
Boom, Two Piece: No Stick, Long: No			Boom Length:	Vac	Boom Check Valve:	
Stick, Long: No Stick Length: 12 FT			Stick, Medium: Stick Check Valve:		Stick, Short: Coupler, Quick:	
Bucket Size: 330-30 I	IN W RIPPER POC	KETS	Thumb, Hydraulic:		Thumb, Mechanical:	
rack Shoe Width/Type: 30 IN To			High Ambient Cooling:		Guarding:	
Engine Tier Rating:			Pattern Changer:	No	Cab Riser:	
Auto-Lube: No			Straight Travel Pedal:		Product Link:	No
Anti-Theft System: No			Comments:	UPPER CAB GUARDING		
GENERAL APPEARANCE						
		REMAR	KS			
	Good					
Shroud	Good					
Engine Enclosure	Fair			NERS HAVE IMPACT DAI LIGHT IMPACT DENTS.	MAGE, MULTIPLE DO	OOR LATCHES
Hood / Stack	Good	INOFERA	ABLE, DOOKS HAVE	LIGHT IMPACT DENTS.		
	Fair	RIGHT F	RONT AND LEFT MII	DDLE CATWALK BENT.		
Fuel Tank	Good					
	Not Applicable					
•	Good					
Drawbar Main Frame Welds	Good	RIGHT FRONT AND LEFT MIDDLE MAIN FRAME HAS IMPACT DENTS.				
	Good	KIOIII I	KONT AND LEFT MI	DDLE MAIN FRAME HAS	SIVII ACT DENTS.	
	Good					
Counterweight	Good					
	Fair			S CLOUDY AND DRY RO		
		RIGHT F	RONT CAB POST HA	S HOLE PUNCHED IN IT	AND A DENT ABOV	E IT.
	Good Fair	l EEL ED	LEFT FRONT CAB HANDRAIL AND LEFT MIDDLE HANDRAIL BENT.			
				DD CONSIDERING VINTA		FOR OVERALL
Paint	Fair	CONDIT			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	Good	SWIVEL	GUARD HAS BEEN F	REMOVED.		
	Good		D DEL TE 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	- P.P.O. W. #~		
	Yes No	ENG, HY	D-PENDING SAMPLI	E RESULTS.		
		GENER A	L WASH AND OPER A	ATOR STATION DETAIL F	OR TRANSPORT AND	DELIVERY EXTR
Cleaning Required	Yes		O WASH HYD COMPA			
Notes						
A GA					p p	2



AFETY ITEMS				
	CODE	REMARKS		
Safety Decals In Place	No			
Safety Decals Legible	No			
ROPS	Not Applicable			
FOPS	Good			
Cab Guards	No			
Horn	Good			
Travel Alarm	NI	TRAVEL ALARM WAS DISCONNECTED AND BATTERIES WERE DEAD.		
Swing Brake	NI			
Brake Hold	NI			
Notes	MACHINE HAD I	DEAD BATTERIES, UNABLE TO OPERATE TO PROVIDE FULL INSPECTION.		







	CODE	REMARKS	
	LODE		
Dash Console	Fair	MULTIPLE PORTIONS OF CONSOLE CRACKED, AND RADIO ANTENNA MISSING,	
		HEADLINER TORN, SEAT SKIRT TORN.	
Meter	Good	HOUR METER READS 1100 HOURS.	
Gauges	Good		
Switches	Good		
Wipers	Poor	WINDSHIELD WIPERS MISSING.	
Air Conditioner	Not Applicable		
Heater	NI		
Interior Lights	Fair	DOME LIGHT UNATTACHED AND INOPERABLE.	
		SEAT BOTTOM TORN AND SEAT BACK WEATHERED AND WORN, LEFT ARM REST DRY ROT	
Seat Cushions / Arm Rests	Fair	AND WEATHERED AND RIGHT ARM REST TORN WITH CHUNKS MISSING, SEAT	
		AJDUSTMENT INOPERABLE.	
Floor Boards	Good		
EMS Panel / Warnings	Good		
Doors	Poor	CAB DOOR IS MISSING.	
Door Latches	Good		
Glass / Mirrors	Fair	RIGHT CAB WINDOW AND FRONT LOWER CAB GLASS MISSING.	
Seat Belt	Good		
77 10 1		LEFT AND RIGHT HYD JOYSTICK VALVES LEAKING INTO OPERATOR STATION, LEFT AND	
Hyd Controls	Fair	RIGHT JOYSTICK DUST BOOTS TORN.	
Parts Book	No		
Safety Manual	No		
O&MM		NEEDS OMM AND SAFETY MANUAL.	
ROPS Cert Plate			
		DE A DID ATTERIES LIMARIE TO OBER ATE TO DROWING BUILT INSPECTION	







































ENGINE

	CODE	REMARKS
Oil Leaks	No	NO LEAKS OBSERVED.
Blow By	No	
Knocking	No	
Compression In Radiator	No	
Water In Oil	No	
Fluid Levels OK?	Yes	
EPA Decal	No	
Anti-freeze Color	GREEN	
Oil Pressure (H/L/W)		
Smoke (B/D/L/W)		
Operating Condition	NI	
Turbocharger / Blower	Good	
Fuel Injection System	Foir	VISUAL ACTIVE LEAKS AROUND FUEL PRIMING PUMP AND FILTERS, NEEDS WASHED AND



Governor	Good	
Engine Supports	Good	
Air Cleaners	Good	
Exhaust / Muffler	Good	
Belts / Pullys	Good	
Oil Filter Condition	Good	
(Cut)	No	
Notes	MACHINE HAD D	EAD BATTERIES, UNABLE TO OPERATE TO PROVIDE FULL INSPECTION.

















COOLING SYSTEM

	CODE	REMARKS
Radiator	Good	
Coolers	Good	
Hoses	Good	
Water Pump	Good	
Fan	Good	
Fan Drive	Good	
Notes	HIGH AMBIENT C	COOLING.



ELECTRICAL, STARTING AND CHARGING SYSTEM

	CODE	REMARKS
Batteries / Cables	Poor	BATTERIES WERE DEAD, STARTED TO CRANK THEN DIED AFTER A FEW ATTEMPTS.
Starter	Good	
Alternator	Good	
Wiring	Good	
Pre-Heater	NI	
Lighting	NI	
Ether Aid	No	
Block Heater	No	
Notes	MACHINE HAD D	FAD BATTERIES LINABLE TO OPERATE TO PROVIDE FULL INSPECTION







FINAL DRIVES

	CODE	REMARKS
Plantaries / Differential	Good	
Housings	Good	
Drive Motors	Fair	RIGHT REAR FINAL DRIVE HOUSING COVERED IN WET OIL, NEEDS WASHED AND ASSESSED FOR REPAIRS.
Guards	Good	
Notes		







воом

	CODE	REMARKS
Pins / Bushings	Ciood	BOOM PINS AND BUSHINGS APPEAR TO HAVE WEAR, MACHINE WOULD NOT START TO PROVIDE FULL ASSESSMENT, FURTHER INSPECTION NEEDED.
Boom Condition	Good	
Boom Pins	Good	
Boom Length		









	CODE	REMARKS
Ding / Duchings	Kinod	STICK PINS AND BUSHINGS APPEAR TO HAVE AVERAGE WEAR FOR AGE AND HOURS ON
Pins / Bushings		MACHINE, MACHINE BATTERIES WERE DEAD, UNABLE TO PROVIDE FULL INSPECTION.
Stick Condition	Good	
Stick Pins	Good	
Stick Length		
Notes		





HV	DR	AII	LICS

HDRAULICS		
CODE	REMARKS	
NI		
Fair	RIGHT BOOM CYLINDER HAS EXCESSIVE VISUAL LEAK PAST ROD SEALS, LEFT BOOM	
	CYLINDER APPEARS TO BE SEEPING PAST ROD SEALS.	
Good		
Fair	BUCKET CYLINDER LEAKING PAST ROD SEALS.	
Not Applicable		
Fair	HOSES ARE WEATHERED AND DRY ROT WITH MINOR FITTINGS LEAKING AROUND	
	MACHINE.	
Fair	PISTON PUMP AND MAIN CONTROL VALVE HAS VISIBLE LEAKS, NEEDS WASHED AND	
	ASSESSED FOR REPAIRS.	
Fair	LINES LEAKING ON BOTTOM OF HYD TANK.	
Good		
NI		
NI		
Good		
No		
	NI Fair Good Fair Not Applicable Fair Fair Good NI NI Good Good Good	

otes MACHINE HAD DEAD BATTERIES, UNABLE TO OPERATE TO PROVIDE FULL INSPECTION





























ATTACHMENTS / WORK TOOLS


	CODE	REMARKS
Hammer	No	
Thumb	No	
Vibratory Plate	No	
Auger	No	
Claw	No	
Crusher	No	
Grapple		
Pulverizer		
Tilting Ditch Bkt	No	
Rake	No	
Shear	No	
Ripper		
Other	No	
Other	No	
Notes	THIS SECTION DO	DES NOT APPLY.

BUCKET

	CODE	REMARKS
Cutting Edge	Not Applicable	
Teeth / Adapters	Good	
Bucket Bottom	Good	
Bucket Sides	Good	




		_
Bucket Linkage	Fair	BUCKET LINKAGE APPEARS TO BE VERY WORN BUT IT SEEMS LIKE THE WRONG PIN SIZES
		ARE BEING USED, NEEDS ASSESSED FOR REPAIRS OR REPLACEMENT PARTS.
Bucket Mounts	Fair	BUCKET MOUNTS APPEAR TO BE WORN, UNABLE TO OPERATE DUE TO DEAD BATTERIES.
(Make / Model)	CAT	
Width	30 IN	
Serial Number	UNREADABLE	
	TAG	
Quick Coupler	No	
Brand		
Notes		
	13	



UNDERCARRIAGE				
	CODE	REMARKS		
Track Frame Left	Good			
Track Frame Right	Good			
Track Pitch				
Pins & Bushings Turned?	No			
Track Shoes Regrousered?	No			
Link Part No.	TREK-7-0040/41			
Link Assemblies				
Track Shoes	30 IN TG			
Carrier Rollers	Good			
Idlers	Good			
Track Rollers	Good			
Cannon	Good			
	LEFT TRACK	RIGHT TRACK	LEFT % WORN	RIGHT % WORN
Link	0.00	0.00	0.00	0.00

Link	0.00	0.00	0.00	0.00
Bushing	0.00	0.00	0.00	0.00
Shoe	0.00	0.00	0.00	0.00
C/Roller	0.00	0.00	0.00	0.00
Idlers	0.00	0.00	0.00	0.00
Rollers	0.00	0.00	0.00	0.00
Sprockets	Poor SPROCKET TEETH ARE SHARP AND WORN, CONSIDERING YEAR OF MACHINE THEY CAN BE RUN OUT.			
	LINABLE TO PROVIDE FULL	LINDERCARRIAGE ASSESSM	MENT DUE TO NOT HAVING	TREK UNDERCARRIAGE

Notes CONVERSION TABLE. UNDERCARRIAGE IS COMPLETE AND OPERATIONAL WITH AVERAGE AMOUNT OF WEAR FOR AGE OF MACHINE.



CODE	REMARKS
Service Needed PM2	500 HOUR SERVICE IS DUE ACCORDING TO TACHOMETER IN CAB.

GENERAL REPAIRS AND REMARKS

Repairs Needed: RIGHT FINAL DRIVE COMPARTMENT LEAK, HYD PISTON PUMP AND CONTROL VALVE COMPARTMENT LEAKS, DAMAGE TO BODY AND CAB, AC INOPERABLE, EXCESSIVE HYD LEAKS, EXCESSIVE OPERATOR STATION REPAIRS.















































